



RAPID SURFACE REPAIR KIT

5 GAL. BUCKET CONTENTS:

Part A	Part B	50 lbs
Resin	Activator	Aggregate
Yield	700 cubic inch	

Installation Tips:

- Saw cut the edge of the area to give yourself a **clean, solid surface edge** to fill up against.
- Use a **15 lbs chisel** to **chip away** loose **substrate**, leaving a **solid surface** for the **epoxy** to **bond** to.
- **Wire wheel** the **surface** and clean off **chemical residues**, leaving a **contaminant-free surface**. Blow out all **dust, debris**.
- Protect any **control joints** from the material, if necessary.
- **Temperature** is very **IMPORTANT!** The material works best at **77 degrees Fahrenheit**.
- Store the buckets in a **temperature controlled environment** for **24 HOURS** prior to mixing. Keep the product **COOL** as long as you can **BEFORE MIXING**.
- If the **concrete floor temperature** is **WARMER** than **77 degrees Fahrenheit**, just remember that the mixture **cures faster** because it will **absorb the heat** from the floor.
- This product mixes at a **1 to 1 RATIO**.
- RSR is amazingly **fast** and will **set up quickly** – **BE PREPARED!**
- Be sure to **MIX ALL** the **aggregate** into the **fluids**...
- Don't leave **aggregate** in the **corners** of the **bucket** or **mixing cups**.

SALES / SUPPORT / TRAINING

ARIZONA – PHOENIX OFFICE	602-258-5599	Dennis Cooper	denniscooper@paramountsupply.com
SALES / TECHNICAL SUPPORT	928-273-4944	Mike Johns	mikejohns@paramountsupply.com
CALIFORNIA SALES	760-468-3397	Jimmy Freeman	jimmyfreeman@paramountsupply.com